

TECHNICAL SANCTION FOR WORKS

Work Name : REPAIR AND MAINTENANCE OF SN UP SCHOOL BUILDING AT KUMBHARI

Work Code : OD/346/3300/116110/391944/00066294

Work Category : Building/ Elementary School

District Name : Balasore

Block Name : Baliapal

Gram Panchayat Name : Kumbhari

Village Name : Kumbhari(Kumari)

The items and Provisions proposed in the estimate are realistic and basically required for this work, prepared & submitted by the preparatory Officer are considered and verified. The items and Provisions proposed in the estimate are in accordance with the relevant specification and Guidelines in vogue. The tasks generated with respect to the items are relevant and suitable.

This Estimate is technically Sanctioned for Rs 399920.52625046/- (Three lakh ninety nine thousand nine hundred twenty rupees five two six two five zero four five five nine four paise only), vide TSR No OD/346/3300/116110/391944/00066294/TS dated: 17-12-2025.

Technical sanction given by : ARUN KUMAR JENA, JE, Baliapal.