

## TECHNICAL SANCTION FOR WORKS

**Work Name :** Const of Guardwall at Dabriguda Jore of Majhiguda GP  
**Work Code :** OD/358/3417/118781/424041/00070167  
**Work Category :** Water Body/ Guard Wall or Retaining Wall or Protection Wall  
**District Name :** Kalahandi  
**Block Name :** Kokasara  
**Gram Panchayat Name :** Majhiguda  
**Village Name :** Majhiguda

The items and Provisions proposed in the estimate are realistic and basically required for this work, prepared & submitted by the preparatory Officer are considered and verified. The items and Provisions proposed in the estimate are in accordance with the relevant specification and Guidelines in vogue. The tasks generated with respect to the items are relevant and suitable.

This Estimate is technically Sanctioned for Rs 299999.4003452/- (Two lakh ninety nine thousand nine hundred ninety nine rupees four zero zero three four five two paise only), vide TSR No OD/358/3417/118781/424041/00070167/TS dated: 18-12-2025.

**Technical sanction given by :** Sourav Kumar Behera, JE, Kokasara.