

TECHNICAL SANCTION FOR WORKS

Work Name : Renovation of Bancho Harijan Sahi Pokhori(Behera Sahi) of Bancho GP

Work Code : OD/361/3449/119387/387061/00063234

Work Category : Water Body/ Tank

District Name : Kendujhar

Block Name : Hatadihi

Gram Panchayat Name : Bancho

Village Name : Bancho

The items and Provisions proposed in the estimate are realistic and basically required for this work, prepared & submitted by the preparatory Officer are considered and verified. The items and Provisions proposed in the estimate are in accordance with the relevant specification and Guidelines in vogue. The tasks generated with respect to the items are relevant and suitable.

This Estimate is technically Sanctioned for Rs 417999.99905906/- (Four lakh seventeen thousand nine hundred ninety nine rupees nine nine nine zero five nine zero six one one seven paise only), vide TSR No OD/361/3449/119387/387061/00063234/TS dated: 25-12-2025.

Technical sanction given by : PRAFULLA CHANDRA BEHERA, JE, Hatadihi.