

TECHNICAL SANCTION FOR WORKS

Work Name : Construction of CD & Guardwall from Banko to Jerei Sahi at Banko

Work Code : OD/361/3445/119307/385416/00070477

Work Category : CD Work/ Drain Masonry or Cement Concrete

District Name : Kendujhar

Block Name : Champua

Gram Panchayat Name : Sunaposi

Village Name : Banko

The items and Provisions proposed in the estimate are realistic and basically required for this work, prepared & submitted by the preparatory Officer are considered and verified. The items and Provisions proposed in the estimate are in accordance with the relevant specification and Guidelines in vogue. The tasks generated with respect to the items are relevant and suitable.

This Estimate is technically Sanctioned for Rs 599999.99720168/- (Five lakh ninety nine thousand nine hundred ninety nine rupees nine nine seven two zero one six eight zero one paise only), vide TSR No OD/361/3445/119307/385416/00070477/TS dated: 26-12-2025.

Technical sanction given by : SABYASACHI NAYAK(AEE), Champua.