

TECHNICAL SANCTION FOR WORKS

Work Name : Construction of Boundary wall of Jhankar Devi Temple at Tota Ambaguda

Work Code : OD/363/3471/119808/428956/00062732

Work Category : Other Infrastructure/ Boundary Wall

District Name : Koraput

Block Name : Koraput

Gram Panchayat Name : Mastiput

Village Name : Mastiput

The items and Provisions proposed in the estimate are realistic and basically required for this work, prepared & submitted by the preparatory Officer are considered and verified. The items and Provisions proposed in the estimate are in accordance with the relevant specification and Guidelines in vogue. The tasks generated with respect to the items are relevant and suitable.

This Estimate is technically Sanctioned for Rs 299184.69450913/- (Two lakh ninety nine thousand one hundred eighty four rupees six nine four five zero nine one three paise only), vide TSR No OD/363/3471/119808/428956/00062732/TS dated: 06-01-2026.

Technical sanction given by : P Santosh Kumar Patro, JE, Koraput.