

## TECHNICAL SANCTION FOR WORKS

**Work Name :** Construction of CC road from incomplete CC road to Bhaskar Senapati House, Senapati Sahi

**Work Code :** OD/346/3309/116321/393686/00074057

**Work Category :** Road/ CC Road

**District Name :** Balasore

**Block Name :** Soro

**Gram Panchayat Name :** Manipur

**Village Name :** Khunta

The items and Provisions proposed in the estimate are realistic and basically required for this work, prepared & submitted by the preparatory Officer are considered and verified. The items and Provisions proposed in the estimate are in accordance with the relevant specification and Guidelines in vogue. The tasks generated with respect to the items are relevant and suitable.

This Estimate is technically Sanctioned for Rs 316999.42322685/- (Three lakh sixteen thousand nine hundred ninety nine rupees four two three two two six eight five paise only), vide TSR No OD/346/3309/116321/393686/00074057/TS dated: 09-01-2026.

**Technical sanction given by :** Taruna Kumar Nandi , JE, Soro.