

TECHNICAL SANCTION FOR WORKS

Work Name : R/R of Naran Pati house Pakha Culvert
Work Code : OD/348/3327/116728/395278/00071335
Work Category : CD Work/ Slab Culvert
District Name : Bhadrak
Block Name : Dhamanagar
Gram Panchayat Name : Dhusuri
Village Name : Narasinghpur

The items and Provisions proposed in the estimate are realistic and basically required for this work, prepared & submitted by the preparatory Officer are considered and verified. The items and Provisions proposed in the estimate are in accordance with the relevant specification and Guidelines in vogue. The tasks generated with respect to the items are relevant and suitable.

This Estimate is technically Sanctioned for Rs 59999.087396118/- (Fifty nine thousand nine hundred ninety nine rupees zero eight seven three nine six one one seven eight eight paise only), vide TSR No OD/348/3327/116728/395278/00071335/TS dated: 10-01-2026.

Technical sanction given by : PRAVAT KUMAR BEHERA, JE, Dhamanagar.