

TECHNICAL SANCTION FOR WORKS

Work Name : Construction of Cement Concrete Road from Dileswar House to Ranjit House at Jaisiria Pada Sublaya

Work Code : OD/373/3587/121752/383868/00069948

Work Category : Road/ CC Road

District Name : Sundargarh

Block Name : Subdega

Gram Panchayat Name : Sublaya

Village Name : Subalaya

The items and Provisions proposed in the estimate are realistic and basically required for this work, prepared & submitted by the preparatory Officer are considered and verified. The items and Provisions proposed in the estimate are in accordance with the relevant specification and Guidelines in vogue. The tasks generated with respect to the items are relevant and suitable.

This Estimate is technically Sanctioned for Rs 304798.99675453/- (Three lakh four thousand seven hundred ninety eight rupees nine nine six seven five four five three paise only), vide TSR No OD/373/3587/121752/383868/00069948/TS dated: 12-01-2026.

Technical sanction given by : SANJAY KUMAR PATEL, JE, Subdega.