

TECHNICAL SANCTION FOR WORKS

Work Name : Const. of Drainage system from Baguni house towards Satyaban house of Jhipabandh village

Work Code : OD/365/3501/120267/388378/00076024

Work Category : Water Body/ Drainage Work

District Name : Mayurbhanj

Block Name : Kusumi

Gram Panchayat Name : Jhipabandha

Village Name : Jhipabandha

The items and Provisions proposed in the estimate are realistic and basically required for this work, prepared & submitted by the preparatory Officer are considered and verified. The items and Provisions proposed in the estimate are in accordance with the relevant specification and Guidelines in vogue. The tasks generated with respect to the items are relevant and suitable.

This Estimate is technically Sanctioned for Rs 389999.98281212/- (Three lakh eighty nine thousand nine hundred ninety nine rupees nine eight two eight one two one two paise only), vide TSR No OD/365/3501/120267/388378/00076024/TS dated: 20-01-2026.

Technical sanction given by : Nabin Kumar Naik, JE, Kusumi.