

TECHNICAL SANCTION FOR WORKS

Work Name : Const. of Jangyan mandap at Maa Biseswari temple, Kialunda

Work Code : OD/369/3538/120918/408661/00073099

Work Category : Religious Structures/ Religious Structures

District Name : Puri

Block Name : Delanga

Gram Panchayat Name : Jenapur

Village Name : Kialanda

The items and Provisions proposed in the estimate are realistic and basically required for this work, prepared & submitted by the preparatory Officer are considered and verified. The items and Provisions proposed in the estimate are in accordance with the relevant specification and Guidelines in vogue. The tasks generated with respect to the items are relevant and suitable.

This Estimate is technically Sanctioned for Rs 413743.5593881/-(Four lakh thirteen thousand seven hundred forty three rupees five five nine three eight eight one paise only), vide TSR No OD/369/3538/120918/408661/00073099/TS dated: 22-01-2026.

Technical sanction given by : LOPAMUDRA PATI, JE, Delanga.