

TECHNICAL SANCTION FOR WORKS

Work Name : Renovation with Toe wall at Dumapada Bhalu bandha tank

Work Code : OD/365/3490/120104/390491/00071842

Work Category : Water Body/ Tank

District Name : Mayurbhanj

Block Name : Baripada

Gram Panchayat Name : Khadisoile

Village Name : Dumapada

The items and Provisions proposed in the estimate are realistic and basically required for this work, prepared & submitted by the preparatory Officer are considered and verified. The items and Provisions proposed in the estimate are in accordance with the relevant specification and Guidelines in vogue. The tasks generated with respect to the items are relevant and suitable.

This Estimate is technically Sanctioned for Rs 314243.46943185/- (Three lakh fourteen thousand two hundred forty three rupees four six nine four three one eight four five five paise only), vide TSR No OD/365/3490/120104/390491/00071842/TS dated: 29-01-2026.

Technical sanction given by : ASHOK KUMAR DAS , JE, Baripada.