

## TECHNICAL SANCTION FOR WORKS

**Work Name :** Repair and Maintenance of Ram Temple at Hirilaguda

**Work Code :** OD/366/3518/120505/427997/00065244

**Work Category :** Religious Structures/ Religious Structures

**District Name :** Nabarangpur

**Block Name :** Nandahandi

**Gram Panchayat Name :** Mentri

**Village Name :** Mentri

The items and Provisions proposed in the estimate are realistic and basically required for this work, prepared & submitted by the preparatory Officer are considered and verified. The items and Provisions proposed in the estimate are in accordance with the relevant specification and Guidelines in vogue. The tasks generated with respect to the items are relevant and suitable.

This Estimate is technically Sanctioned for Rs 499967.07320249/- (Four lakh ninety nine thousand nine hundred sixty seven rupees zero seven three two zero two four nine paise only), vide TSR No OD/366/3518/120505/427997/00065244/TS dated: 29-01-2026.

**Technical sanction given by :** SAUMYA RANJAN PANDA, JE, Nandahandi.