

TECHNICAL SANCTION FOR WORKS

Work Name : Const. of cc road from Prabhakar Biswal house Biswal sahi Ainari

Work Code : OD/346/3309/116311/393969/00063258

Work Category : Road/ CC Road

District Name : Balasore

Block Name : Soro

Gram Panchayat Name : Antapur

Village Name : Ainri

The items and Provisions proposed in the estimate are realistic and basically required for this work, prepared & submitted by the preparatory Officer are considered and verified. The items and Provisions proposed in the estimate are in accordance with the relevant specification and Guidelines in vogue. The tasks generated with respect to the items are relevant and suitable.

This Estimate is technically Sanctioned for Rs 79999.483101198/-(Seventy nine thousand nine hundred ninety nine rupees four eight three one zero one one nine eight paise only), vide TSR No OD/346/3309/116311/393969/00063258/TS dated: 30-01-2026.

Technical sanction given by : Raisen Murmu, JE, Soro.