

TECHNICAL SANCTION FOR WORKS

Work Name : Repair & Maint. of AWC at Anantapur-2

Work Code : OD/346/3309/116311/394015/00064861

Work Category : Building/ Banking Facility Building

District Name : Balasore

Block Name : Soro

Gram Panchayat Name : Antapur

Village Name : Anantapur

The items and Provisions proposed in the estimate are realistic and basically required for this work, prepared & submitted by the preparatory Officer are considered and verified. The items and Provisions proposed in the estimate are in accordance with the relevant specification and Guidelines in vogue. The tasks generated with respect to the items are relevant and suitable.

This Estimate is technically Sanctioned for Rs 44999.744697001/- (Forty four thousand nine hundred ninety nine rupees seven four four six nine seven zero zero one paise only), vide TSR No OD/346/3309/116311/394015/00064861/TS dated: 30-01-2026.

Technical sanction given by : Raisen Murmu, JE, Soro.