

## TECHNICAL SANCTION FOR WORKS

**Work Name :** Repair of road from R.D road to Sukumari Lenka house via: Bharat Behera house

**Work Code :** OD/346/3309/116327/393992/00073391

**Work Category :** Road/ CC Road

**District Name :** Balasore

**Block Name :** Soro

**Gram Panchayat Name :** Sajanpur

**Village Name :** Sajanpur

The items and Provisions proposed in the estimate are realistic and basically required for this work, prepared & submitted by the preparatory Officer are considered and verified. The items and Provisions proposed in the estimate are in accordance with the relevant specification and Guidelines in vogue. The tasks generated with respect to the items are relevant and suitable.

This Estimate is technically Sanctioned for Rs 14999.990740124/-(Fourteen thousand nine hundred ninety nine rupees nine nine zero seven four zero one two four paise only), vide TSR No OD/346/3309/116327/393992/00073391/TS dated: 31-01-2026.

**Technical sanction given by :** Monalisa Pati , JE, Soro.