

## TECHNICAL SANCTION FOR WORKS

**Work Name :** Construction of River bathing steps at karchabadi

**Work Code :** OD/353/3360/117509/413756/00071224

**Work Category :** Water Body/ Bathing Ghat or Changing Room

**District Name :** Gajapati

**Block Name :** Mohona

**Gram Panchayat Name :** Karachabadi

**Village Name :** Karchabadi

The items and Provisions proposed in the estimate are realistic and basically required for this work, prepared & submitted by the preparatory Officer are considered and verified. The items and Provisions proposed in the estimate are in accordance with the relevant specification and Guidelines in vogue. The tasks generated with respect to the items are relevant and suitable.

This Estimate is technically Sanctioned for Rs 299998.79197402/- (Two lakh ninety nine thousand nine hundred ninety eight rupees seven nine one nine seven four zero one nine two six paise only), vide TSR No OD/353/3360/117509/413756/00071224/TS dated: 01-02-2026.

**Technical sanction given by :** Pradeepta Kumar Sethi, JE, Mohona.