

TECHNICAL SANCTION FOR WORKS

Work Name : Constn. Of Bathing Steps with Changing Room at Rengali Talabandha

Work Code : OD/349/3331/116832/417700/00078965

Work Category : Water Body/ Bathing Ghat or Changing Room

District Name : Boudh

Block Name : Kantamal

Gram Panchayat Name : Rengali

Village Name : Rengali

The items and Provisions proposed in the estimate are realistic and basically required for this work, prepared & submitted by the preparatory Officer are considered and verified. The items and Provisions proposed in the estimate are in accordance with the relevant specification and Guidelines in vogue. The tasks generated with respect to the items are relevant and suitable.

This Estimate is technically Sanctioned for Rs 299999.20562863/- (Two lakh ninety nine thousand nine hundred ninety nine rupees two zero five six two eight six two six eight paise only), vide TSR No OD/349/3331/116832/417700/00078965/TS dated: 14-02-2026.

Technical sanction given by : Babun Kumar Sahu, JE, Kantamal.