

TECHNICAL SANCTION FOR WORKS

Work Name : CONST OF CULVERT AT SUNDHIGUDA TO GUNDAL ROAD

Work Code : OD/363/3467/119725/429197/00075699

Work Category : CD Work/ Slab Culvert

District Name : Koraput

Block Name : Boipariguda

Gram Panchayat Name : Kenduguda

Village Name : Disariguda

The items and Provisions proposed in the estimate are realistic and basically required for this work, prepared & submitted by the preparatory Officer are considered and verified. The items and Provisions proposed in the estimate are in accordance with the relevant specification and Guidelines in vogue. The tasks generated with respect to the items are relevant and suitable.

This Estimate is technically Sanctioned for Rs 399999.98331764/- (Three lakh ninety nine thousand nine hundred ninety nine rupees nine eight three three one seven six four paise only), vide TSR No OD/363/3467/119725/429197/00075699/TS dated: 21-02-2026.

Technical sanction given by : Umesh, JE, Boipariguda.