

TECHNICAL SANCTION FOR WORKS

Work Name : Repair & Maintenance of Baruan-2 AWC Building

Work Code : OD/352/3349/117240/402538/00068832

Work Category : Building/ AWC

District Name : Dhenkanal

Block Name : Bhuban

Gram Panchayat Name : Baruan(B)

Village Name : Baruan

The items and Provisions proposed in the estimate are realistic and basically required for this work, prepared & submitted by the preparatory Officer are considered and verified. The items and Provisions proposed in the estimate are in accordance with the relevant specification and Guidelines in vogue. The tasks generated with respect to the items are relevant and suitable.

This Estimate is technically Sanctioned for Rs 44999.636601454/- (Forty four thousand nine hundred ninety nine rupees six three six six zero one four five three nine nine six paise only), vide TSR No OD/352/3349/117240/402538/00068832/TS dated: 21-02-2026.

Technical sanction given by : Lopamudra Mahanta, JE, Bhuban.