

TECHNICAL SANCTION FOR WORKS

Work Name : Repair & Maintenance of AWC Building at Gunduria

Work Code : OD/365/3488/120067/387559/00067620

Work Category : Building/ AWC

District Name : Mayurbhanj

Block Name : Bahalda

Gram Panchayat Name : Anlajodi

Village Name : Gunduria

The items and Provisions proposed in the estimate are realistic and basically required for this work, prepared & submitted by the preparatory Officer are considered and verified. The items and Provisions proposed in the estimate are in accordance with the relevant specification and Guidelines in vogue. The tasks generated with respect to the items are relevant and suitable.

This Estimate is technically Sanctioned for Rs 202037.29729727/- (Two lakh two thousand thirty seven rupees two nine seven two nine seven two seven paise only), vide TSR No OD/365/3488/120067/387559/00067620/TS dated: 23-02-2026.

Technical sanction given by : LAXMAN KUMAR MURMU, JE, Bahalda.