

## TECHNICAL SANCTION FOR WORKS

**Work Name :** Repair and restoration of road from dukhiram soren house to Rabana marandi house

**Work Code :** OD/346/3305/116239/393152/00105702

**Work Category :** Road/ CC Road

**District Name :** Balasore

**Block Name :** Nilgiri

**Gram Panchayat Name :** Jadida

**Village Name :** Jadida

The items and Provisions proposed in the estimate are realistic and basically required for this work, prepared & submitted by the preparatory Officer are considered and verified. The items and Provisions proposed in the estimate are in accordance with the relevant specification and Guidelines in vogue. The tasks generated with respect to the items are relevant and suitable.

This Estimate is technically Sanctioned for Rs 29999.993095332/-(Twenty nine thousand nine hundred ninety nine rupees nine nine three zero nine five three three two paise only), vide TSR No OD/346/3305/116239/393152/00105702/TS dated: 11-03-2026.

**Technical sanction given by :** BABITA BEHERA, JE, Nilgiri.