

TECHNICAL SANCTION FOR WORKS

Work Name : CONST OF CULVERT AT BANUGUDA

Work Code : OD/363/3467/119718/429271/00067939

Work Category : CD Work/ Slab Culvert

District Name : Koraput

Block Name : Boipariguda

Gram Panchayat Name : Chandrapada

Village Name : Chandrapada

The items and Provisions proposed in the estimate are realistic and basically required for this work, prepared & submitted by the preparatory Officer are considered and verified. The items and Provisions proposed in the estimate are in accordance with the relevant specification and Guidelines in vogue. The tasks generated with respect to the items are relevant and suitable.

This Estimate is technically Sanctioned for Rs 299999.8800678/- (Two lakh ninety nine thousand nine hundred ninety nine rupees eight eight zero zero six seven eight paise only), vide TSR No OD/363/3467/119718/429271/00067939/TS dated: 11-03-2026.

Technical sanction given by : Ashish kumar tiriya, JE, Boipariguda.