

TECHNICAL SANCTION FOR WORKS

Work Name : Repair and restoration of road from sita majhi house to Kanaka majhi house to Chandanpur

Work Code : OD/346/3305/116239/393152/00105729

Work Category : Road/ CC Road

District Name : Balasore

Block Name : Nilgiri

Gram Panchayat Name : Jadida

Village Name : Jadida

The items and Provisions proposed in the estimate are realistic and basically required for this work, prepared & submitted by the preparatory Officer are considered and verified. The items and Provisions proposed in the estimate are in accordance with the relevant specification and Guidelines in vogue. The tasks generated with respect to the items are relevant and suitable.

This Estimate is technically Sanctioned for Rs 17999.994431936/- (Seventeen thousand nine hundred ninety nine rupees nine nine four four three one nine three six paise only), vide TSR No OD/346/3305/116239/393152/00105729/TS dated: 13-03-2026.

Technical sanction given by : BABITA BEHERA, JE, Nilgiri.