

TECHNICAL SANCTION FOR WORKS

Work Name : Construction of Guard Wall at Gandibed RD Road to Anguru Behera house

Work Code : OD/346/3308/116307/394131/00110379

Work Category : Road/ Guard Wall

District Name : Balasore

Block Name : Simulia

Gram Panchayat Name : Markona

Village Name : Ria

The items and Provisions proposed in the estimate are realistic and basically required for this work, prepared & submitted by the preparatory Officer are considered and verified. The items and Provisions proposed in the estimate are in accordance with the relevant specification and Guidelines in vogue. The tasks generated with respect to the items are relevant and suitable.

This Estimate is technically Sanctioned for Rs 344153.54688158/-(Three lakh forty four thousand one hundred fifty three rupees five four six eight eight one five eight paise only), vide TSR No OD/346/3308/116307/394131/00110379/TS dated: 16-03-2026.

Technical sanction given by : Bhakta Ranjan Mohanty, JE, Simulia.