

TECHNICAL SANCTION FOR WORKS

Work Name : Repair and restoration of road from dhobasila shiba temple to rabindra ghadei house

Work Code : OD/346/3305/116237/393148/00105746

Work Category : Road/ CC Road

District Name : Balasore

Block Name : Nilgiri

Gram Panchayat Name : Dhobasila

Village Name : Dhobasila

The items and Provisions proposed in the estimate are realistic and basically required for this work, prepared & submitted by the preparatory Officer are considered and verified. The items and Provisions proposed in the estimate are in accordance with the relevant specification and Guidelines in vogue. The tasks generated with respect to the items are relevant and suitable.

This Estimate is technically Sanctioned for Rs 29999.99555422/- (Twenty nine thousand nine hundred ninety nine rupees nine nine five five five four two two paise only), vide TSR No OD/346/3305/116237/393148/00105746/TS dated: 17-03-2026.

Technical sanction given by : BAIDYANATH SINGH, JE, Nilgiri.