

TECHNICAL SANCTION FOR WORKS

Work Name : Improvement of Balunkeswar Temple Beautification at Marthapur

Work Code : OD/352/3349/117251/402611/00101916

Work Category : Religious Structures/ Religious Structures

District Name : Dhenkanal

Block Name : Bhuban

Gram Panchayat Name : Marthapur

Village Name : Marthapur

The items and Provisions proposed in the estimate are realistic and basically required for this work, prepared & submitted by the preparatory Officer are considered and verified. The items and Provisions proposed in the estimate are in accordance with the relevant specification and Guidelines in vogue. The tasks generated with respect to the items are relevant and suitable.

This Estimate is technically Sanctioned for Rs 399999.56855892/-(Three lakh ninety nine thousand nine hundred ninety nine rupees five six eight five five eight nine two paise only), vide TSR No OD/352/3349/117251/402611/00101916/TS dated: 18-03-2026.

Technical sanction given by : Lopamudra Mahanta, JE, Bhuban.