

TECHNICAL SANCTION FOR WORKS

Work Name : Construction of guard wall from Kubera mahanta to NH20 at Hundula village under Palaspanga GP

Work Code : OD/361/3452/119466/385992/00065839

Work Category : Water Body/ Guard Wall or Retaining Wall or Protection Wall

District Name : Kendujhar

Block Name : Kendujhar Sadar

Gram Panchayat Name : Palaspanga

Village Name : Hundula

The items and Provisions proposed in the estimate are realistic and basically required for this work, prepared & submitted by the preparatory Officer are considered and verified. The items and Provisions proposed in the estimate are in accordance with the relevant specification and Guidelines in vogue. The tasks generated with respect to the items are relevant and suitable.

This Estimate is technically Sanctioned for Rs 150000.00259269/- (One lakh fifty thousand rupees zero zero two five nine two six nine paise only), vide TSR No OD/361/3452/119466/385992/00065839/TS dated: 19-03-2026.

Technical sanction given by : Ranjan Kumar Swain, JE, Kendujhar Sadar.