

## TECHNICAL SANCTION FOR WORKS

**Work Name :** Const of Dress Changing Room at Mandiaguda Kusulipent and Paching

**Work Code :** OD/363/3477/119893/428582/00073810

**Work Category :** Water Body/ Bathing Ghat or Changing Room

**District Name :** Koraput

**Block Name :** Narayan Patana

**Gram Panchayat Name :** Kumbhari

**Village Name :** Mandiaguda

The items and Provisions proposed in the estimate are realistic and basically required for this work, prepared & submitted by the preparatory Officer are considered and verified. The items and Provisions proposed in the estimate are in accordance with the relevant specification and Guidelines in vogue. The tasks generated with respect to the items are relevant and suitable.

This Estimate is technically Sanctioned for Rs 299999.68758212/- (Two lakh ninety nine thousand nine hundred ninety nine rupees six eight seven five eight two one two paise only), vide TSR No OD/363/3477/119893/428582/00073810/TS dated: 20-03-2026.

**Technical sanction given by :** Sravani Padhy, JE, Narayan Patana.