

TECHNICAL SANCTION FOR WORKS

Work Name : Repair and Maintenance of road from Bhagirathi Panda house to Malik Sahi

Work Code : OD/346/3309/116332/394006/00115828

Work Category : Road/ CC Road

District Name : Balasore

Block Name : Soro

Gram Panchayat Name : Tentei

Village Name : Tentei

The items and Provisions proposed in the estimate are realistic and basically required for this work, prepared & submitted by the preparatory Officer are considered and verified. The items and Provisions proposed in the estimate are in accordance with the relevant specification and Guidelines in vogue. The tasks generated with respect to the items are relevant and suitable.

This Estimate is technically Sanctioned for Rs 143787.99509659/- (One lakh forty three thousand seven hundred eighty seven rupees nine nine five zero nine six five nine zero zero two paise only), vide TSR No OD/346/3309/116332/394006/00115828/TS dated: 30-03-2026.

Technical sanction given by : Subal Chandra Mallik , JE, Soro.